



Replacement Sheet

1/17




FIG. 1

Replacement Sheet

2/17





FIG. 2A

Replacement Sheet




FIG. 2B

Replacement Sheet

4/17




FIG. 3A




FIG. 3B

Replacement Sheet

6/17




FIG. 4

Replacement Sheet

7/17




FIG. 5

Replacement Sheet

8/17




FIG. 6A

(Replacement Sheet)

9/17




FIG. 6B

(Replacement Sheet)

10/17




FIG. 7A

Replacement Sheet

11/17




FIG. 7B

(Replacement Sheet)

12/17




FIG. 8

900




FIG. 9

Replacement Sheet

13/17

1000

1002

BROADBAND INTERFACE UNIT (BIntU) TRANSCEIVER REQUESTS SERVICE FROM THE DATA DISTRIBUTION CONTROL CENTER

1004

ROUTING CHANNEL OF PRESCRIBED BANDWIDTH FOR USER DATAGRAM PROTOCOL WITH VALUE ADDED (UDPVA) PACKETS ESTABLISHED BETWEEN THE BIntU TRANSCEIVER AND THE DATA DISTRIBUTION CHANNEL

1006

SERIES OF UDPVA PACKETS TRANSMITTED TO FORM CONTINUOUS AUDIO/VIDEO STREAM FROM THE DATA DISTRIBUTION CONTROL CENTER TO THE BIntU TRANSCEIVER. RECORD OF EACH UDPVA PACKET MAINTAINED

1008

FOR EACH UDPVA PACKET TRANSMITTED FROM THE DATA DISTRIBUTION CONTROL CENTER TO THE BIntU TRANSCEIVER, A CORRESPONDING RETURN PACKET IS TRANSMITTED FROM THE BIntU TRANSCEIVER TO THE DATA DISTRIBUTION CONTROL CENTER

1010

EACH ONE OF THE SERIES OF UDPVA PACKETS IN CONTINUOUS AUDIO/VIDEO STREAM COMPARED TO THE CORRESPONDING RETURN PACKET TO DETERMINE WHICH UDPVA PACKETS WERE RECEIVED AT THE BIntU TRANSCEIVER

1012

DID CORRESPONDING RETURN PACKET RETURN TO DATA DISTRIBUTION CENTER OVER PRESCRIBED PERIOD ?

NO

1014

REASON FOR MISSING PACKETS
CONSIDERED AND FAULTY
TRANSMISSION CORRECTED


YES

1016

TRANSMISSION
MAINTAINED

FIG. 10

Replacement Sheet



Replacement Sheet




FIG. 11B

Replacement Sheet

16/17




FIG. 12A

(Replacement Sheet)

17/17




FIG. 12B